

ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards ⁽¹⁾ only). Update 31 March 2022

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration ⁽²⁾		
L-3 Communications	MVT HR	<i>Hardware configuration:</i> MVT-HR <i>Detection Algorithm:</i> V7.3.2 <i>Auxiliary Software:</i> v.5.9.0 <i>Auxiliary Hardware:</i> No tray	1⁽³⁾ (ECAC/EU expired)	14/05/2013

ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards (1) only). Update 31 March 2022

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration ⁽²⁾		
Rapiscan	RTT80	<i>System Hardware:</i> RTT 80 <i>Detection Algorithm Version:</i> 1.0.1 <i>Auxiliary Software:</i> v.6.0.3 <i>Auxiliary Hardware:</i> No tray	1 ⁽³⁾ (ECAC/EU expired)	08/10/2010

ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards ⁽¹⁾ only). Update 31 March 2022

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration ⁽²⁾		
Smiths Detection	HI-SCAN 10080 EDX-2is	<i>Hardware</i> HS 10080 EDX-2is	1 ⁽³⁾ (ECAC/EU expired)	03/09/2012
		<i>Detection Algorithm</i> 06-50-09		
		<i>Auxiliary Software:</i> ES-03-10-1-89-01		
		<i>Auxiliary Hardware:</i> No tray		

Notes:

⁽¹⁾ **ECAC/EU expired standard:** The use of equipment configurations meeting an expired standard is not recommended to ECAC Member States from the expiration date set out in Doc 30, Part II (Security). EU Member States shall not use equipment meeting an expired standard, in accordance with EU Regulations)

⁽²⁾ Information on **configuration** was provided by the equipment manufacturer as part of the testing process.

⁽³⁾ **Standard 1** for Explosive Detection Systems expired on 01 January 2014 (Ref ECAC Doc 30, Part II (Security) point 12.4.2.2; Ref Commission implementing Regulation (EU) 185/2010 Annex 12.4.2.2)