

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Analogic	ConneCT	Hardware: ConneCT Detection Algorithm: 9.04 Auxiliary Hardware: Scarabee tray (P/N 21-06027-01) CONOPS: 16-01519 Rev.00-2016	C2	20/9/2017 *05/02/2021 *Correction of entry
Analogic	ConneCT	Hardware: ConneCT Detection Algorithm: 9.07 Auxiliary Hardware: Scarabee tray (P/N 21-06027-01) CONOPS: 16-01519 Rev.00-2016	C2	23/3/2018 *05/02/2021 *Correction of entry
Analogic	ConneCT	Hardware: ConneCT Detection Algorithm: 9.07 Auxiliary Hardware: Herbert tray (P/N 42112482) CONOPS: 16-01519 Rev.03-2018	C2	20/12/2018 *05/02/2021 *Correction of entry
Analogic	ConneCT	Hardware: ConneCT Detection Algorithm: 9.11 Auxiliary Hardware: Vanderlande tray (P/N 095527-727) CONOPS: 16-01519 Rev.03-2018	C2	20/12/2018 *05/02/2021 *Correction of entry
Analogic	ConneCT	Hardware: ConneCT Detection Algorithm: 9.15.01 Auxiliary Hardware: Herbert tray (P/N 42112482) CONOPS: 16-01519 Rev.03-2018	C2	04/03/2019 *05/02/2021 *Correction of entry
Analogic	ConneCT	Hardware: ConneCT Detection Algorithm: 9.15.01 Auxiliary Hardware: Vanderlande tray (P/N 095527-727) CONOPS: 16-01519 Rev.03-2018	C2	04/03/2019 *05/02/2021 *Correction of entry

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> 9.15.01 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> 16-01519 Rev.03-2018	C2	04/03/2019 *05/02/2021 *Correction of entry
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> v9.17.01 <i>Auxiliary Hardware:</i> Vanderlande tray (P/N 095527-727) <i>CONOPS:</i> 16-01519 Rev.03-2018	C3	04/03/2019 *05/02/2021 *Correction of entry
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> 9.17.02 <i>Auxiliary Hardware:</i> Herbert tray (P/N 42112482) <i>CONOPS:</i> 16-01519 Rev.03-2018	C3	04/03/2019 *05/02/2021 *Correction of entry
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> 9.17.02 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> 16-01519 Rev.03-2018	C3	04/03/2019 *05/02/2021 *Correction of entry
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> 9.19.04 <i>Auxiliary Hardware:</i> Herbert (P/N 42112482) MacDonald Humfrey tray (P/N 12043-SLT) Vanderlande (P/N 095527-727) <i>CONOPS:</i> 16-01519-rev03-2018	C3	29/11/2019 *05/02/2021 *Correction of entry

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> v9.23.05 <i>Auxiliary Hardware:</i> Herbert tray (P/N 101019470) <i>CONOPS:</i> 16-01519 Rev.03-2018	C3	24/02/2021
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> v9.21.09 <i>Auxiliary Hardware:</i> Vanderlande tray (P/N 095527-727) <i>CONOPS:</i> 16-01519 Rev.03-2018	C3	24/02/2021
Analogic	ConneCT	<i>Hardware:</i> ConneCT <i>Detection Algorithm:</i> v9.23.04 <i>Auxiliary Hardware:</i> MacDonald Humfrey (P/N 12043-SLT) <i>CONOPS:</i> 16-01519 Rev.03-2018	C3	24/02/2021

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Gilardoni	FEP ME 640 AMX	<i>Hardware:</i> 37548400-001 <i>Detection Algorithm:</i> 3AUE0294-005 <i>Auxiliary Hardware:</i> Gilardoni tray (P/N 55203181) <i>CONOPS:</i> 37640500-001 37640500-004	C1	23/3/2018 CCM (04/02/2021)

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 200.3.0 <i>Auxiliary Hardware:</i> Scarabee tray SSL01_XA001_NH <i>CONOPS:</i> CONOPS 1 SRT	C2	6/6/2017
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 200.3.0 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> CONOPS 1 SRT	C2	6/6/2017
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 201.1.1 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> Detect 1000 user guide Revision 3.0	C2	24/1/2018
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 201.1.1 <i>Auxiliary Hardware:</i> Scarabee tray SSL01_XA001_NH <i>CONOPS:</i> Detect 1000 user guide Revision 3.0	C2	24/1/2018
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 205.0.0 <i>Auxiliary Hardware:</i> Scarabee tray SSL01_XA001_NH <i>CONOPS:</i> Detect 1000 user guide Revision 3.0	C2	19/10/2018 *26/10/2018 *Correction of entry

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 205.0.0 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> Detect 1000 user guide Revision 3.0	C2	19/10/2018 *26/10/2018 *Correction of entry
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 314.0.1 <i>Auxiliary Hardware:</i> Scarabee tray SSL01_XA001_NH <i>CONOPS:</i> Detect 1000 user guide Revision 3.0	C3	19/10/2018 *26/10/2018 *Correction of entry
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 314.0.1 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> Detect 1000 user guide Revision 3.0	C3	19/10/2018 *26/10/2018 *Correction of entry
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 326.0.0 <i>Auxiliary Hardware:</i> Vanderlande Bandeja Scannojet tray <i>CONOPS:</i> Mfg. No. 1000D1000v4.0	C3	15/07/2019
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 326.0.0 <i>Auxiliary Hardware:</i> OneTray tray (P/N OT_VAS007) OneTray tray (P/N OT-VAS013) OneTray tray (P/N OT-VAS015) OneTray tray (P/N OT-VAS016) <i>CONOPS:</i> IDSS_REP-077_Detect1000_ConOps_Rev0	C3	25/03/2020 CCM (22/09/2020) *19/03/2021 *Correction of entry

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 329.0.0 <i>Auxiliary Hardware</i> Herbert tray (P/N 91280AS) <i>CONOPS:</i> Mfg. No. 1000D1000v4.0	C3	20/01/2021
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 332.1.0 <i>Auxiliary Hardware</i> Cassioli tray (P/N S030012FPLT) <i>CONOPS:</i> IDSS_REP-077_Detect1000_ConOps_Rev0	C3	20/01/2021
IDSS Holdings Inc.	Detect 1000	<i>Hardware:</i> Detect 1000 <i>Detection Algorithm:</i> 332.1.0 <i>Auxiliary Hardware</i> WO tray (P/N W-280819-000) <i>CONOPS:</i> IDSS_REP-077_Detect1000_ConOps_Rev0	C3	20/01/2021

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.2.5 <i>Auxiliary Hardware:</i> Scarabee tray SSL01_XA001_NH <i>CONOPS:</i> 8100-26282-OM	C2	6/6/2017
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.2.5 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> 8100-26282-OM	C2	6/6/2017
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.2.5 <i>Auxiliary Hardware:</i> Herbert tray 91280AS <i>CONOPS:</i> 8100-26282-OM	C2	6/6/2017
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.4.14 <i>Auxiliary Hardware:</i> Herbert tray 91280AS <i>CONOPS:</i> 8100-26282-OM	C3	24/1/2018
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.4.15 <i>Auxiliary Hardware:</i> Scarabee tray SSL01_XA001_NH <i>CONOPS:</i> 8100-26282-OM	C3	24/1/2018

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.4.18 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> 8100-26282-OM	C3	24/1/2018
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.4.25 <i>Auxiliary Hardware:</i> Scarabee tray (P/N SSL01_XA001_NH) <i>CONOPS:</i> 8100-26282-OM	C3	20/12/2018
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan	<i>Hardware:</i> 1000-10001-CS <i>Detection Algorithm:</i> EDS_1.4.25 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> 8100-26282-OM	C3	20/12/2018
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan HS	<i>Hardware:</i> 1000-10001-CSU <i>Detection Algorithm:</i> EDS-1.4.33 <i>Auxiliary Hardware:</i> Vanderlande tray (P/N 095527-727) <i>CONOPS:</i> 8100-34802-OM	C3	10/06/2020 *19/03/2021 *Correction of entry
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan HS	<i>Hardware:</i> 1000-10001-CSU <i>Detection Algorithm:</i> EDS-1.4.41 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> 8100-34802-OM	C3	10/06/2020 *19/03/2021 *Correction of entry

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Leidos (Previously: L3 Technologies Implant Sciences Corp.)	ClearScan HS	<i>Hardware:</i> 1000-10001-CSU <i>Detection Algorithm:</i> EDS-1.4.42 <i>Auxiliary Hardware:</i> Scarabee tray (P/N SSL01_XA001_NH) <i>CONOPS:</i> 8100-34802-OM	C3	10/06/2020 *19/03/2021 *Correction of entry

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Nuctech	Kylin	<i>Hardware:</i> DHV 1.0 <i>Detection Algorithm:</i> v3.5.7 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray v4 P10128 revA <i>CONOPS:</i> v1.0	C1	24/1/2018
Nuctech	Kylin	<i>Hardware:</i> DHV 1.0 <i>Detection Algorithm:</i> v3.5.9 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray v4 P10128 revA <i>CONOPS:</i> v1.0	C2	24/1/2018
Nuctech	CX6040D	<i>Detection Algorithm:</i> Eda V1.0.0 <i>Auxiliary Hardware:</i> Nuctech NUC680 tray (P/N v1) Vanderlande Scannojet tray v4 P10128 revA <i>CONOPS:</i> CONOPS CX6040D V1.0	C1	19/10/2018
Nuctech	CX6040D	<i>Detection Algorithm:</i> Eda V1.0.0 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray v4 P10128 revA <i>CONOPS:</i> CONOPS CX6040D V1.0	C1	19/10/2018
Nuctech	Kylin Ti	<i>Hardware:</i> Kylin Ti DHV 1.0 <i>Detection Algorithm:</i> v3.6.10 <i>Auxiliary Hardware:</i> Nuctech NUC680 tray (P/N v1) <i>CONOPS:</i> Kylin Ti v1.0	C3	20/12/2018
Nuctech	Kylin MV	<i>Hardware:</i> DHV 1.0 <i>Detection Algorithm:</i> v7.0.3 <i>Auxiliary Hardware:</i> Nuctech NUC680 tray (P/N v1) <i>CONOPS:</i> v1.0	C2	04/03/2019

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Nuctech	Kylin MV	<i>Hardware:</i> DHV 1.0 <i>Detection Algorithm:</i> v7.0.3 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray v4 P10128 revA <i>CONOPS:</i> v1.0	C2	04/03/2019
Nuctech	Kylin Ti	<i>Hardware:</i> Kylin Ti DHV 1.0 <i>Detection Algorithm:</i> v3.6.10 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray v4 P10128 revA <i>CONOPS:</i> Kylin Ti v1.0	C3	04/03/2019
Nuctech	Kylin Ti	<i>Hardware:</i> Kylin Ti DHV 1.0 <i>Detection Algorithm:</i> v3.6.12 <i>Auxiliary Hardware:</i> Nuctech NUC680 tray (P/N v3) <i>CONOPS:</i> Kylin Ti CONOPS v1.2	C3	20/01/2021
Nuctech	Kylin Ti	<i>Hardware:</i> Kylin Ti DHV 1.0 <i>Detection Algorithm:</i> v3.6.13 <i>Auxiliary Hardware:</i> Cassioli tray (P/N S030008FPLT) <i>CONOPS:</i> Kylin Ti CONOPS v1.2	C3	20/01/2021
Nuctech	CX7555D	<i>Hardware:</i> CX7555D.A03N <i>Detection Algorithm:</i> EDA 1.0.2 <i>Auxiliary Hardware:</i> Nuctech NUC680 tray (P/N v3); Vanderlande Scannojet tray 95527-727 (P10128 revA); MacDonald Humfrey tray (12043-SLT). <i>CONOPS:</i> CONOPS_CX7555D_EDSCB_V1.0_20190716	C1	25/03/2020

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Nuctech	Kylin Ti	<i>Hardware:</i> DHV 2.0 <i>Detection Algorithm:</i> V3.6.23 <i>Auxiliary Hardware:</i> Alfyma tray (P/N RDBA18-PART-000-B) Vanderlande Scannojet tray (P/N 095527-727 / P10128 revA) MacDonald Humfrey tray (P/N 12043-SLT) <i>CONOPS:</i> Kylin Ti - CONOPS v1.2 (2019/07/03)	C3	24/02/2021

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Rapiscan	620DV	<i>Hardware:</i> 620DV <i>Detection Algorithm:</i> 4.517 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 101005244) <i>CONOPS:</i> D00370 Rev.1	C1	20/12/2018
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> 9.04 <i>Auxiliary Hardware:</i> Scarabee tray (P/N 21-06027-01) <i>CONOPS:</i> 101014944 Rev 2	C2	28/05/2018 *05/02/2021 *Correction of entry
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> 9.07 <i>Auxiliary Hardware:</i> Scarabee tray (P/N 21-06027-01) <i>CONOPS:</i> 101014944 Rev 2	C2	28/05/2018 *05/02/2021 *Correction of entry
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> 9.07 <i>Auxiliary Hardware:</i> Herbert tray (P/N 42112482) <i>CONOPS:</i> 101014944 Rev 2	C2	20/12/2018 *05/02/2021 *Correction of entry
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> 9.11 <i>Auxiliary Hardware:</i> Vanderlande tray (P/N 095527-727) <i>CONOPS:</i> 101014944 Rev 2	C2	20/12/2018 *05/02/2021 *Correction of entry
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> 9.15.01 <i>Auxiliary Hardware:</i> Herbert tray (P/N 42112482) <i>CONOPS:</i> 101014944 Rev 2	C2	04/03/2019 *05/02/2021 *Correction of entry

Manufacturer	Equipment			Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾			
Rapiscan	920CT	Hardware:	920CT	C2	04/03/2019
		Detection Algorithm:	9.15.01		*05/02/2021
		Auxiliary Hardware:	Vanderlande tray (P/N 095527-727)		*Correction of entry
		CONOPS:	101014944 Rev 2		
Rapiscan	920CT	Hardware:	920CT	C2	04/03/2019
		Detection Algorithm:	9.15.01		*05/02/2021
		Auxiliary Hardware:	MacDonald Humfrey tray (P/N 12043-SLT)		*Correction of entry
		CONOPS:	101014944 Rev 2		
Rapiscan	920CT	Hardware:	920CT	C3	04/03/2019
		Detection Algorithm:	v9.17.01		*05/02/2021
		Auxiliary Hardware:	Vanderlande tray (P/N 095527-727)		*Correction of entry
		CONOPS:	101014944 Rev 2		
Rapiscan	920CT	Hardware:	920CT	C3	04/03/2019
		Detection Algorithm:	9.17.02		*05/02/2021
		Auxiliary Hardware:	Herbert tray (P/N 42112482)		*Correction of entry
		CONOPS:	101014944 Rev 2		
Rapiscan	920CT	Hardware:	920CT	C3	04/03/2019
		Detection Algorithm:	9.17.02		*05/02/2021
		Auxiliary Hardware:	MacDonald Humfrey tray (P/N 12043-SLT)		*Correction of entry
		CONOPS:	101014944 Rev 2		

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> 9.19.04 <i>Auxiliary Hardware:</i> Herbert tray (P/N 42112482) MacDonald Humfrey tray (P/N 12043-SLT) Vanderlande tray (P/N 095527-727) <i>CONOPS:</i> 101014944 Rev 2	C3	29/11/2019 *05/02/2021 *Correction of entry
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> v9.23.05 <i>Auxiliary Hardware:</i> Herbert tray (P/N 101019470) <i>CONOPS:</i> 101014944 Rev 2	C3	24/02/2021
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> v9.21.09 <i>Auxiliary Hardware:</i> Vanderlande tray (P/N 095527-727) <i>CONOPS:</i> 101014944 Rev 2	C3	24/02/2021
Rapiscan	920CT	<i>Hardware:</i> 920CT <i>Detection Algorithm:</i> v9.23.04 <i>Auxiliary Hardware:</i> MacDonald Humfrey (P/N 12043-SLT) <i>CONOPS:</i> 101014944 Rev 2	C3	24/02/2021

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-12-23 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	19/12/2016
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-15-12 <i>Auxiliary Hardware:</i> Herbert tray 91280AS (P/N 34460688) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-15-13 <i>Auxiliary Hardware:</i> Herbert tray 91280AS (P/N 34460688) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-16-23 <i>Auxiliary Hardware:</i> Herbert tray 91280AS (P/N 34460688) <i>CONOPS:</i> 95595885 (2016/09/26)	C2	6/6/2017
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-15-12 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-15-13 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-16-23 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C2	6/6/2017
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-70-23 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray (P/N P10128 / 095527-727) <i>CONOPS:</i> 95596016	C2	04/03/2019
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-19-23 <i>Auxiliary Hardware:</i> Vanderlande Scannojet tray (P/N 10128 / 095527-727) <i>CONOPS:</i> 95596016	C1	19/10/2018
Smiths Detection	HI-SCAN 6040aTiX	<i>Hardware:</i> 6040aTiX <i>Detection Algorithm:</i> 09-15-13 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) Smiths Detection tray 2 (P/N 34482148) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	20/12/2018 CCM (21/10/2020)

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040aTiX	Hardware: 6040aTiX Detection Algorithm: 09-18-13 Auxiliary Hardware: MacDonald Humfrey tray (P/N 34460689) CONOPS: 95595885 (2016/09/26)	C1	23/3/2018
Smiths Detection	HI-SCAN 6040aTiX	Hardware: 6040aTiX Detection Algorithm: 09-18-24 Auxiliary Hardware: MacDonald Humfrey tray (P/N 34460689) CONOPS: 95595885 (2016/09/26)	C2	23/3/2018
Smiths Detection	HI-SCAN 6040aTiX	Hardware: 6040aTiX Detection Algorithm: 09-16-23 Auxiliary Hardware: Smiths Detection tray (P/N 34486990) Smiths Detection tray 2 (P/N 34482148) CONOPS: 95595885 (2016/09/26)	C2	20/9/2017 CCM (21/10/2020)

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-15-14 <i>Auxiliary Hardware:</i> Herbert tray 91280AS (P/N 34460688) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-17-16 <i>Auxiliary Hardware:</i> Herbert tray 91280AS (P/N 34460688) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-17-26 <i>Auxiliary Hardware:</i> Herbert tray 91280AS (P/N 34460688) <i>CONOPS:</i> 95595885 (2016/09/26)	C2	6/6/2017
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-15-14 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-15-16 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C1	6/6/2017
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-16-26 <i>Auxiliary Hardware:</i> Schoeller Allibert tray 2A021 (P/N 11112352) <i>CONOPS:</i> 95595885 (2016/09/26)	C2	6/6/2017
Smiths Detection	HI-SCAN 7555aTiX	<i>Hardware:</i> 7555aTiX <i>Detection Algorithm:</i> 09-71-27 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	24/02/2021

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection (Previously: Morpho Detection)	XDi	<i>Hardware:</i> XDi <i>Detection Algorithm:</i> XDi-CBS-C-v1.0 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 2.13	C1	6/6/2017 *26/10/2018 *Correction of entry

Manufacturer	Equipment			Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾			
Smiths Detection	HI-SCAN 6040-2is HR	Hardware:	6040-2is HR	C1	6/6/2017
		Detection Algorithm:	09-15-17		
		Auxiliary Hardware:	Herbert tray 91280AS (P/N 34460688)		
		CONOPS:	95595885 (2016/09/26)		
Smiths Detection	HI-SCAN 6040-2is HR	Hardware:	6040-2is HR	C1	6/6/2017
		Detection Algorithm:	09-15-19		
		Auxiliary Hardware:	Herbert tray 91280AS (P/N 34460688)		
		CONOPS:	95595885 (2016/09/26)		
Smiths Detection	HI-SCAN 6040-2is HR	Hardware:	6040-2is HR	C1	6/6/2017
		Detection Algorithm:	09-15-17		
		Auxiliary Hardware:	Schoeller Allibert tray 2A021 (P/N 11112352)		
		CONOPS:	95595885 (2016/09/26)		
Smiths Detection	HI-SCAN 6040-2is HR	Hardware:	6040-2is HR	C1	6/6/2017
		Detection Algorithm:	09-15-20		
		Auxiliary Hardware:	Schoeller Allibert tray 2A021 (P/N 11112352)		
		CONOPS:	95595885 (2016/09/26)		
Smiths Detection	HI-SCAN 6040-2is HR	Hardware:	6040-2is HR	C1	20/9/2017 CCM (21/10/2020)
		Detection Algorithm:	09-15-20		
		Auxiliary Hardware:	Smiths Detection tray (P/N 34486990) Smiths Detection tray 2 (P/N 34482148)		
		CONOPS:	95595885 (2016/09/26)		

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040-2is HR	<i>Hardware:</i> 6040-2is HR <i>Detection Algorithm:</i> 09-19-19 <i>Auxiliary Hardware:</i> Vanderlande tray (P/N P10128 / 095527-727) <i>CONOPS:</i> 95596016 (2017/09/26)	C1	20/12/2018
Smiths Detection	HI-SCAN 6040-2is HR	<i>Hardware:</i> 6040-2is HR <i>Detection Algorithm:</i> 09-15-20 <i>Auxiliary Hardware:</i> Smiths Detection tray 3 (P/N 34493797) <i>CONOPS:</i> 95596016 rev. 02 (2020/03/01)	C1	20/01/2021

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-10-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	23/3/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-14-00 <i>Auxiliary Hardware:</i> Scarabee tray (P/N SSL01_XA003_NH) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-20-00 <i>Auxiliary Hardware:</i> Scarabee tray (P/N SSL01_XA003_NH) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-20-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-14-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-20-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-27-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 (2017/09/26)	C3	19/10/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-27-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C3	19/10/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-20-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-14-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-20-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-14-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-20-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C2	28/5/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-27-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 (2017/09/26)	C3	19/10/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-27-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 (2017/09/26)	C3	19/10/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-31-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) Scarabee tray (P/N SSL01_XA003_NH) Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 Rev. 1 (2017/09/26)	C2	20/12/2018

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040CTiX	<i>Hardware:</i> 6040CTiX <i>Detection Algorithm:</i> 20-36-00 <i>Auxiliary Hardware:</i> Smiths (P/N 34486990) Mac Donald Humfrey (P/N34460689) Scarabee (P/N SSL01_XA003_NH) <i>CONOPS:</i> 95596016	C3	29/11/2019
Smiths Detection	HI-SCAN 6040CTiX	<i>Hardware:</i> 6040CTiX <i>Detection Algorithm:</i> 20-41-00 <i>Auxiliary Hardware:</i> Smiths (P/N 34486990) Mac Donald Humfrey (P/N34460689) Scarabee (P/N SSL01_XA003_NH) <i>CONOPS:</i> 95596016	C3	29/11/2019
Smiths Detection	HI-SCAN 6040CTiX	<i>Hardware:</i> 6040CTiX <i>Detection Algorithm:</i> 20-30-00 <i>Auxiliary Hardware:</i> Smiths Detection tray 2 (P/N 34482148) Vanderlande (P10128 / 095527-727) <i>CONOPS:</i> 95596016	C2 & C3	05/09/2019
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-30-00 <i>Auxiliary Hardware:</i> Scarabee tray (P/N SSL01_XA003_NH) <i>CONOPS:</i> 95596016 Rev. 1 (2017/09/26)	C3	20/12/2018

Manufacturer	Equipment		Standard ⁽²⁾	Notification
	Designation	Configuration ⁽¹⁾		
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-30-00 <i>Auxiliary Hardware:</i> MacDonald Humfrey tray (P/N 34460689) <i>CONOPS:</i> 95596016 Rev. 1 (2017/09/26)	C3	20/12/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-30-00 <i>Auxiliary Hardware:</i> Smiths Detection tray (P/N 34486990) <i>CONOPS:</i> 95596016 Rev. 1 (2017/09/26)	C3	20/12/2018
Smiths Detection	HI-SCAN 6040 CTiX	<i>Hardware:</i> 6040 CTiX <i>Detection Algorithm:</i> 20-50-00 <i>Auxiliary Hardware:</i> OneTray tray (P/N OT_VAS013) Cassioli tray (P/N S030012FPLT) Smiths Detection tray 3 (P/N 34496512) <i>CONOPS:</i> 95596016 rev.02 (2020/03/01)	C3	24/02/2021

Notes:

⁽¹⁾ Information on configuration is provided by the equipment manufacturer as part of the testing process.

⁽²⁾ The Concept of Operations (CONOPS) applied for EDSCB equipment depends on the EDSCB Standard achieved:

Standard C1: Screening requires the divestment of electronics and liquids, aerosols and gels (LAGs).

Standard C2: Allows screening of baggage containing portable computers and other large electrical items.

Standard C3: Allows screening of baggage containing portable computers and other large electrical items and LAGs.

Standard C4: Same CONOPS as Standard C3.

Disclaimer: Listed EDSCB configurations had not been tested for hold baggage performance under the CEP