Country	IMPLEMENTATION STATUS OF ECAC RECOMMENDATION INT.S/11-1	Legal Source	Documents Required	Conditions & Additional Requirements	Contact Address for Public Inquiries	Additional Information
ARMENIA	NO					
AUSTRIA	ECAC recommendation entirely implemented with some conditions: • flight document available • submission of flight plan to cross FIR-Boundary (no need for civil a/c in VRF to Fed. Rep. Germany) • insurances laid down concluded • customs regul. complied • rules and reg rules of the air observed • availability of certificate from State of register or equivalent • only COM transceiver 760 channels and 25KHZ permitted Installation serviceable emergency transmitter • day light with visual rules only • low altitude over crowds or densely populated areas prohibited Note: a/c in flight testing not covered because of separate rules and approval required.	Implementation by the Austrian CAA available at Austro Control published in AIP Part1 General, GEN 1.5-3. More general conditions in airworthiness notice LTH22 http://www.austrocontrol.at/images/LTH_LFA_ACE 022_tcm586-47434.pdf	Restricted certificate or airworthiness or permit to fly Airplane Flight Manual Insurance certificate Noise certificate a/c in flight testing not covered because of separate rules and approval required	Yes; limitations applicable: • submission prior departure for flight plan crossing boundary • customs regulation must be complied with • Pilots should observe Austrian rules and regulations • only Com transceiver 760 channels 25 KHZ permitted • ELT required • day light with visual rules only low altitude over crowds or densely populated areas prohibited Note: a/c in flight testing not covered because of separate rules and approval required	Publication in AIP (see para5) via Austro Control GmbH, Schnichgasse 11, 1030 Wien, Austria www.austrocontrol.at Responsible advisors: www.austrocontrol.at/lf a/ lufthahrzeuge/lufttechti gkeit_und_zertifizierun g/a_kontakt/kontakt.shtml	Austria is working on procedure and technical standards to certify homebuilt aircraft for limited IFR operation. IFR under day VFR condition only.
AZERBAIJAN	NO					
BELGIUM	NO					
CROATIA	ECAC recommendation entirely implemented.	De-facto standard not legally published.Way CAA considers acceptable for handling approvals of foreign aircraft without ICAO CofA	Those required by State that granted the certificate	No	flight- authorization@ccaa.hr Tel.: +385 1 2369 350 Fax: +385 1 2369 351 AFTN: LDZGYAYX Internet: http://ccaa.hr/default. aspx?id=11	N/A
CYPRUS	ECAC recommendation entirely implemented.	ECAC Recommendations discussed internally and circulars distributed to responsible personnel for subject areas if recommendations are to be followed and implemented. No publication for the above information but the Department examines each application for overflight taking into	Certificate of registration Flight crew licenses Aircraft insurance documents Radio license Application for Overflight	A/c must be equipped with Mode C transponder	Cyprus AIP Gen 1.1.1 Tel: +357 22404100 & +357 22404101 Fax: +357 22766552 & +357 22404220 director@dca.mc.gov.cy y ais@dca.mcw.gov.cy	N/A

Country	IMPLEMENTATION STATUS OF ECAC RECOMMENDATION INT.S/11-1	Legal Source	Documents Required	Conditions & Additional Requirements	Contact Address for Public Inquiries	Additional Information
DENMARK	ECAC recommendations entirely implemented, provided that the aircraft: • is registered in an ECAC MS • has completed its flight test period • the maximum take-ff mass does not exceed 2,730kg		A valid third party liability insurance certificate meeting the requirements in the Air Navigation Act § 130 cf. AIP Denmark GEN 1.2		<u>=256@Itemid</u> =294	Document to be forwarded to DCAA: • flight permit /special certificate of airworthiness issued by CAA of country of registry • operational limitations • registration certificate • insurance certificate meeting the requirements in the Air Navigation act §130 cf. AIP Denmark GEN 1.2 • Noise certificate For flights in the North Atlantic (Faeroe Islands and Greenland) additional documentation may be requested to show that safe is possible (weight and balance, endurance and fuelsystem, emergency equipment). According to BL 9-10 CAA Denmark's scheme of charges 2011, the issuance of a Danish validation will be invoiced with a fee of DKK 3.340,- A Danish validation may be issued for up to 90 days. Authorisation of flights over Denmark with home-built aircraft classified as ULM, Ultralight or Microlight are handled by the Danish
ESTONIA	NO					IlltralighT Flying Association (DIII FII)
FINLAND	ECAC recommendation entirely implemented.	Finish Aviation Act 1194/2009 Section 7 published in Finnish AIP GEN 1.8-3 (https://ais.fi/ais/eaip/e n/index.tmt	Documents mentioned in Finnish Aviation Act 1194/2009 Section 66	_	n/index.htm For public inquiries: lentotoiminta@fcaa.fi	Interested to allow all commercially built ultralight aeroplanes having a valid CoA or permit to fly to fly to Finnish territory without any special permission.
France	the aircraft type is unknown or originates from a country, French aviation authority: DGCA, is not use to working with, specific additional information is required.	Case 1: Code de l'aviation civile Art. D. 133-20 Case 2 and 3: Code des transports Art. L. 6211-1	to fly issued by the ECAC MS and documents required on board by the State concerned	No specific requirements or limitations. For case 2 and 3 the French permit to fly is granted for a max. period of 6 months	laissez- passer.DCS@aviation- civile.gouv.fr	_
GERMANY	ECAC recommendation entirely implemented.	General permission published in form of a notice for airmen (NfL), AIP	Legal liability insurance CofA or permit to fly	Flights must be: • conducted between SR and SS only • according VFR • prior entering/departing the FR of Germany • be equipped with VF transmitter/receiver with frequency range 117.975 to 137 MHz, 25 kHz A fligh plan must be filed	Luftfahrt-Bundesamt (LBA), einflug@lba.de	

Country	IMPLEMENTATION STATUS OF ECAC RECOMMENDATION INT.S/11-1	Legal Source	Documents Required	Conditions & Additional Requirements	Contact Address for Public Inquiries	Additional Information
GREECE	ECAC recommendations entirely implemented.	Presidential Decree P.D. 283/2001 published in Gazette of Greek Government No 197A on 5/9/2001	Certificate of Registration Radio Station License Airworthiness Certificate or permit to fly including operational limitation of the aircraft Insurance certificate	Home-built a/c shall comply with airspace restrictions/ requirements (id use of transponder)	Hellenic CAA Flight Standards Division Airworthiness Section P.O. Box 70360 166 10 Glyfada Fax: +302109973013 email: ypa@hcaa.gr iyr: www.hcaa.gr	_
HUNGARY	NO					
ICELAND	NO					
IRELAND	ECAC recommendation entirely implemented.	The recommendation has been implemented by way of a General Exemption and is published as an Aeronautical Notice.	The Certificates of Registration and the original permit to fly or equivalent issued by the State of registration.	Yes, as set out in Aeronautical Notice A19	The Irish Aviation Authority, Safety Regulation Division, The Times Building, Dolier Street, Dublin 2 Ireland +353 1 6718655 www.iaa.ie	Pilot licensing requirements are not covered by the ECAC exemption and should be resolved with the Irish Aviation Authority before a flight to Ireland. The Irish Aviation Authority before a flight to Ireland. The Irish Aviation Authority Flight Operations Department should be contacted at: +353 1 618655 — www.iaa.ie
ITALY	ECAC recommendation entirely implemented.	ENAC Circular NAV 74	No	No	Direzione Regolazione Certificazione Prodotti Aeronautici regolazione.prodottiaer onautici@enac.gov.it	
LATVIA	ECAC recommendation entirely implemented.	Regulation of Cabinet of Ministers No 661 (issued 8/09/206) and No 573 (issued 15/07/2006). AIP publication under preparation. Information enclosed in a VFR Guide for Latvia http://www.yfrguide.co	Certificate of Registration A/c radio licence Insurance Certificate of Airwortiness or Permit to fly	No	http://vfrguide.com	
MALTA	ECAC recommendation partially implemented as permits are time restricted	No specific legislation. Draft policy and procedures available for consultation and expected to be officially published this year on Transport Malta's Web site: www.transport.gov.mt	Permit to fly Insurance Radio station licence Pilot's Licence Flight Permission issued by the Civil Aviation Directorate, Transport Malta Registration Certificate	See No2	dutyofficer.cad@transp ort.gov.mt	Once a request is received by the Duty Management Officers, other Units within the Civil Aviation Directorate are involved with the evaluation of the request until the permission is granted. The Airworthiness Inspectorate Unit is consulted with regard to the permit to fly while the Personnel Licensing Unit will check the flight crew
MONACO	NO					

Country	IMPLEMENTATION STATUS OF ECAC RECOMMENDATION INT.S/11-1	Legal Source	Documents Required	Conditions & Additional Requirements	Contact Address for Public Inquiries	Additional Information
NETHERLAND S	ECAC recommendation entirely implemented.	Ministerial Degree publication by AIC-A 16- 02 from 2/05/2002	Certificate of Registration Airworthiness Certificate or permit to fly Restrictions and limitations related to the CifA or PtF Radio Station License Proof of insurance Pilot documents	Yes, for visits of a limited duration. Long time stay or permanent stationing are not allowed.	IVW Info-centre PO Box 90653 2509 LR Den Haag Tel. +31 88 489 0000 Fax +31 70 456 24 24 info@ivwnl	
NORWAY	ECAC recommendation entirely implemented.	Recommendation published in AIP and information is enclosed in a VFR Guide for Norway published and updated each year. http://www.caa.no/ga/a rticle21781.ece	Certificate of registration Aircraft radio licence Insurance Permit to fly (or equal) Flight manual included weight and balance Documentation checked if the aircraft is cubicet to an	No	http://www.caa.no/ga/ article21781.ece	A new OPS regulation regarding homebuilt aircraft is underway. This regulation will probably affect visiting aircraft and same proposed restrictions will apply when operating within Norwegian airspace.
POLAND	Wholly implemented	Art. 50 of the Aviation Act adopted on 3/07/2002 (OJ of laws of 2006, No 100, item 696) and executive regulations adopted on the basis of Art. 53	Certificate of airworthiness or permit to fly Insurance certiticate Pilot licence or equivalent	No	_	
ROMANIA	"overflight within the national airspace is authorized and performed in compliance with the provisions of the Romanian Government Decision concerning the approval of the overflight within the national airspace as well as of the conditions established for the civil aircraft landing and takeoff on/from other terrains or water surfaces other than certified aerodromes."	Decision of the Romanian Government www.caa.ro	airworthiness certificate or permit to fly a/c registration/identification insurance policy first/last takeoff on/from Romanian territory be performed at an international airport published in AIP Romania Approval of the owner and local authorities	No	gabriel.tubac@caa.ro +40 21 208 15 99 mihai.voicu@caa.ro +40 21 208 15 11 remus.dogaru@caa.ro +40 21 208 15 14 dan.hadarca@caa.ro +40 21 208 15 96	
SAN MARINO	NO					
SERBIA	ECAC recommendation entirely implemented.	_	_	_	snicic@cad.gov.rs	_

Country	IMPLEMENTATION STATUS OF ECAC RECOMMENDATION INT.S/11-1	Legal Source	Documents Required	Conditions & Additional Requirements	Contact Address for Public Inquiries	Additional Information
SLOVAK REP.	ECAC recommendation entirely implemented.	Published in the AIP-SR Information for visiting pilots provided by the Slovak Federation of Ultralight Flying, entitled to manage operations ofthese aircraft within the territory of the Slovak	No	PPL licence requirement	http://www.caa.sk/kon takt-e.htm clerk@caa.sk operations@caa.sk http://www.sful.sk/def ault.aspx sluk@sful.sk	
SLOVENIA	ECAC recommendation entirely implemented.	Aircraft (Official Gazette of the Republic of Slovenia No 107/2008) (Slovene version only) and Regulation on omebuilt aircraft (Official Gazette of SFRJ No 19/1982) (Slovene version only).Regulation on Ultralight Aircraft — website: http://zakonodaja.gov.s i/rpsi/r01/predpis_PRAV 811.html Regulation on homebuilt aircraft — webiste:	insurance which is valid for the territory of the Republic of Slovenia • This type of aircraft should comply with the	Please see answer number 6	Slovenia control, Slovenian Air Navigation Services, Limited info@sloveniacontrol.si http://www.sloveniaco ntrol.si/eng/about- us/contact-information	
SPAIN	NO					
SWEDEN	ECAC recommendation entirely implemented.		The documents required in the origin country for the amateur- built aircraft should be kept onboard the aircraft when entering Swedish border.	It is required that the aircraft has completed its flight test period. En route charges from Eurocontrol: 60 sjr/flight.		
SWITZERLAN D	ECAC recommendation partially implemented: VFR night and IFR flights are only allowed if the aircraft fulfills the Swiss minimum requirements	Art. 2 of Federal Aviation Law. www.foca.admin.ch www.admin.ch	Certificate of registration CofA or permit to fly Insurance AFM Log book Noise certificate	No	.ch/fachleute/lufttechni	The ECAC Recommendation INT.S/11-1 should easily be available on the Web, even on Google it is difficult to find.

Country	IMPLEMENTATION STATUS OF ECAC RECOMMENDATION INT.S/11-1	Legal Source	Documents Required	Conditions & Additional Requirements	Contact Address for Public Inquiries	Additional Information
The former Yugoslav Republic of Macedonia	ECAC recommendation entirely implemented.	Flight Approval Regulation (CAA No 2.11) Information published in AIP under GEN 1.2.6	Flight Approval Regulation (CAA No 2.11) Information published in AIP under GEN 1.2.6 • Certificate of Registration, • Certificate of Airworthiness or Permit to fly • Special autorisation issued in accordance with Art. 29 para 2 of the Aviation Act, in cases of active area scan • Other documents depending on the kind of activity of aircraft used in general aviation	Same as item 6		Contact address provided in AIP, under GEN 1.2.2 Tel: +389 2 311 93 81 Fax: +389 2 311 57 08 agramatikov@caa.gov.mk eandonova@caa.gov.mk
UKRAINE	NO					
UNITED KINGDOM	ECAC recommendation implemented in 1984. In 2008 additional requirements to monitor aa/c utilising arrangements to ensure that a/c were entering UK on visits and not abusing provision to avoid UK registration for residency		The exemption under GC No 6 requires: • a Permit to fly or equivalent • incurance certificate • a/c registration • conditions or limitations pages associated • pilot operating handbook or equivalent	Limitation to day VFR flying		Applications and Approvals Department 2E, Aviation House Gatwick Airport South West Sussex RH6 0YR United Kingdom Tel.+44 1293 768374 Fax +44 1293 573860 aanda@caa.co.uk http://www.caa.co.uk/default.aspx?ca tid=1407&pagetype=90&pageid=8129